



Acc.V 5.0kV Magn Det WD 10.0um
 30.0kV 3.0 25000x SE 11.5 Fixed



SEM image showing a cross-section of a polymer matrix. A central vertical feature, possibly a crack or a void, is visible. The matrix has a granular texture. A scale bar at the bottom indicates 10 μm. Technical data at the bottom left includes: AccV 30.0kV, Spot 3.0, Magn 2000x, Det SE, Wt 11.2, and Power 1.00w.

Fig. 1

2/8

*Fig. 2*

3/8






Fig. 3

4/8

A



B

*Fig. 4*

5/8





Fig. 5

6/8

*Fig. 6*

7/8





Fig. 7

8/8

*Fig. 8*